

Map ID
Direction
Distance
Elevation

MAP FINDINGS

EDR ID Number
EPA ID Number

Site

Database(s)

400
WSW
1/2-1
0.644 mi.
3398 ft.

MANHOLE #53063
W. 23 ST & MERMAID AVE
BROOKLYN, NY

NY Spills S104511452
N/A

Relative:
Higher

Actual:
2 ft.

SPILLS:

Name: MANHOLE #53063
Address: W. 23 ST & MERMAID AVE
City,State,Zip: BROOKLYN, NY
Spill Number/Closed Date: 0000037 / 2002-01-22
Facility ID: 0000037
Facility Type: ER
DER Facility ID: 68055
Site ID: 72016
DEC Region: 2
Spill Cause: Unknown
Spill Class: C4
SWIS: 2401
Spill Date: 2000-04-02

Investigator: JHOCONNE
Referred To: Not reported
Reported to Dept: 2000-04-02
CID: 322
Water Affected: Not reported
Spill Source: Unknown
Spill Notifier: Affected Persons
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 2000-04-02
Spill Record Last Update: 2002-01-24
Spiller Name: UNKNOWN
Spiller Company: Unknown
Spiller Address: UNKNOWN
Spiller Company: 999
Contact Name: Not reported
DEC Memo: "Prior to Sept, 2004 data translation this spill Lead_DEC Field was O'CONNELL Con Ed e2mis #130690 Notes: 4-2-00 2150hrs 2qts unknown oil on 300gal water in manhole 53063. Took liquid sample. 4-3-00 0600hrs LSN 00-03131 <1ppm PCB 4-3-00 1210hrs Cleanup completed by double washing with slix. Liquids removed by tanker, solids by vactor. No leaking equipment. No sump."

Remarks: "2 qts of unk oil on 300 gal of water in manhole - samples taken and clean up pending results - con ed #130690"

All Materials:

Site ID: 72016
Operable Unit ID: 821734
Operable Unit: 01
Material ID: 288307
Material Code: 0066A
Material Name: unknown petroleum
Case No.: Not reported
Material FA: Petroleum
Quantity: 1.00
Units: G

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

Recovered: .00
Oxygenate: Not reported